

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**DZ623**  
**WSW**  
**1/2-1**  
**0.925 mi.**  
**4886 ft.**

**MANHOLE 71777**  
**WEST 29TH STREET+MERMAID**  
**BROOKLYN, NY**

**NY Spills** **S106007990**  
**N/A**

**Site 2 of 4 in cluster DZ**

**Relative:**  
**Higher**

**SPILLS:**

**Actual:**  
**3 ft.**

Name: MANHOLE 71777  
Address: WEST 29TH STREET+MERMAID  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0206813 / 2003-01-28  
Facility ID: 0206813  
Facility Type: ER  
DER Facility ID: 79674  
Site ID: 86912  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C3  
SWIS: 2401  
Spill Date: 2002-10-01  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 2002-10-01  
CID: 282  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Affected Persons  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2002-10-01  
Spill Record Last Update: 2003-01-28  
Spiller Name: SAME  
Spiller Company: UNKNOWN FOR NOW  
Spiller Address: SAME  
Spiller Company: 001

Contact Name: CHARLIE MCCARTHY

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL e2mis no. 145-332: 01-OCT-2002 02:35 HRS. B/Q EQUIPMENT GROUP. SPLICER V.DINEEN EMP# 41974 REPORTS: WHILE ON LOCATION TO PRESSURE TEST VS5993 (100' SOUTH) FOUND IN LINE THE HOLE M71777 A UNDIAPERABLE SHEEN ON APPROX. 1000 GAL'S OF WATER. SPILL IS CONTAINED. NO SEWERS OR WATER WAYS APPEAR TO BE AFFECTED. THERE IS NOT NOW NOR WAS THERE PRIOR FIRE INVOLVEMENT. THERE IS NOT NOW NOR WAS THERE PRIOR SMOKE INVOLVEMENT. THERE WERE NO INJURIES RELATED TO THIS INCIDENT. THERE ARE NO INCLEMENT WEATHER CONDITIONS OR HAZARD THAT CONTRIBUTED TO THIS SPILL. NO KNOWN SUMP OR PUMP IN STRUCTURE. NO KNOWN SEWER CONNECTION PRESENT. NO PRIVATE PROPERTY AFFECTED. OWNER OF SUBSTANCES IS UNKNOWN. NO KNOWN SUBSTANTIAL CRACKS IN STRUCTURE. ENVIR. TAG# 08305 PLACED. 1 LIQ. SAMPLE TAKEN. UPDATE 10-1-02 1200 HRS CHEM LAB # 02-09183-001 OIL ID ANALYSIS INDICATES PRESENCE SIMILAR TO A DIELECTRIC FLUID ALSO # 02-09183-001 4 PPM Update - 1605hrs - 10/1/02 S. Adedapo env. ops crew reports while performing cleanup found earthen sump. Will remove from 24 hr deminimus program. Update - 2100hrs - 10/1/02 J. Dekanchuk reports clean up stopped. Tanker broke down. Structure is making water. UPDATE: 10/2/02 - 1300 F. DELLATORRE - ENV. OPS., REPORTS CLEANUP

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Remarks:

COMPLETED BY DOUBLE WASHING STRUCTURE WITH BULLDOG. LIQUID WASTE REMOVED BY TANKER. SOLID WASTE REMOVED BY VACTOR. SUMP WAS SEALED. TAG # 08305 REMOVED. STRUCTURE MAKES WATER THROUGH FLOOR."  
"THEY HAVE A SHEEN ON 1,000 GALLONS OF WATER SPILL BEING TREATED AS A 24 HOUR DIMINUMIS CON ED 145332 NO SEWERS OR WATERWAYS NO FIRE NO SMOKE NO TRANSFORMER INVOLVED "

All Materials:

Site ID: 86912  
Operable Unit ID: 858578  
Operable Unit: 01  
Material ID: 517408  
Material Code: 0064A  
Material Name: unknown material  
Case No.: Not reported  
Material FA: Other  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported